

# General Environmental Incident Summary

**Incident:** 4054      **Date/Time Notice:** 3/30/2016      1210      **DEM Incident No:**  
**Responsible Party:** Basin Concrete, Inc  
**Date Incident:** 3/29/2016      **Time Incident:** 1130      **Duration:** 1 hours  
**County:** Williams      **Twp:** 154      **Rng:** 100      **Sec:** 18      **Qtr:**  
**Lat:** 48.15947      **Long:** -103.58280      **Method:** Interpolation from map  
**Location Description:** get on CR 9 from 1804, then drive approximately 3.5 miles north.

**Submitted By:** Osa Osagiede      **Affiliation:** Works for BCI  
**Address:** 5023 138th Ave NW  
**City:** Williston      **State:** ND      **Zip:** 58801

## Received By:

**Contact Person:** Osa Osagiede  
2023 138th Ave NW  
Williston , ND 58801

**Distance Nearest Occupied Building:** 150 Feet      **Release Contained:** Yes

**Type of Incident:** Tank Leak

**Description of Released Contaminant:** 20 gallons of Diesel Fuel, and 15 gallas of Hydraulic Oil

**Volume Spilled:** 35.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** Unknown

## Cause of Incident:

Basin Concrete, Inc Driver was traveling south bound on Hwy 85B (CR9) when the drive shaft broke and fell out of the Hydrovac truck he was driving. The drive shaft damaged a fuel line and 2 hydraulic lines resulting in the spill of 20 gallons of diesel fuel and 15 gallons of Hydraulic oil.

## Risk Evaluation:

Immediate risk after the spill was potentially flammable environment due to the diesel fuel spilled.

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

I believed the likelihood of fire was low, due to the quick response of Basin Concrete, Inc Emergency Response Team.

## Action Taken or Planned:

The driver immediately stopped when he notice 200 yards from the spot he notice the drive shaft damage.

He was able to contain the fuel line leak. the 2 hydraulic took another 45 minutes to stop the leak from the broken lines.

Most of the leak was contained on the asphalt (road), The driver call dispatch and the company immediately sent another a work crew to help with the clean up.

Absorbent sand was placed on the spill on the road to absorb the liquid which was later scooped up.

In the mean time, the damage truck was towed to Basin Concrete, Inc' yard.

After the clean up was completed, the crew left the location at approximately 2:45pm.

**Wastes Disposal Location:** 2 barrels of contaminated dirt used in the clean was disposed at Tervita waste disposal facility.

**Agencies Involved:**

### **Updates**

---

**Date:** 3/30/2016    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

According to the incident summary, this spill impacted areas not associated with E & P location. Follow-up is necessary.

---

**Date:** 4/19/2016    **Status:** Inspection

**Author:** Crowdus, Kory

**Updated Volume:**

**Notes:**

At location 4/19/2016, at 11:10 a.m. Impacted area was to the north side of roadway shoulder. Area approximately 150 yards X 5 feet has been scraped. No remaining impacts seen at this time. No further follow-up is required.